

City of Springfield
Water Pollution Control Section
Pollution Complaint/Report Form

Date 11/14/95

Report From:

☒ Citizen
☐ Fire Dept.
☐ Public Information Office
☐ Health Department
☐ Other

Received By: R. LUMAN
Referred To: G. PABST
Date of Incident: last week

Complainant Information:

Name DID NOT LEAVE NAME
Address _____
Phone _____
Directions (if needed): _____

Responsible Party Information:

Name SEMINOLE AMOCO
Address 2152 S. Glenstone
Phone _____

Possible contamination of: ☐ soil ☐ groundwater
☐ surface water what body? _____
☒ other SANITARY SEWER

Other pertinent information: _____

Who to contact:

☐ DNR 417-837-6950
☐ DNR 314-634-2436
☐ EPA 913-236-3778
☐ Fire Dept. 864-1719
☐ Police Dept. 864-1719
☐ Bob Schaefer
☐ CU 831-8320
☐ Street Dept.

☐ Health Dept.
☐ Sewer Maintenance
☐ Sewer Construction
☐ Chemtrec 1-800-424-9300
☐ DOT
☐ NRC 1-800-424-8802
☐ Other

Details of incident: CUSTOMER OBSERVED DUMPING OF
ANTIFREEZE DOWN A DRAIN (5-6 GALLONS) WHILE
HAVING HIS AUTO SERVICED.

Action needed: CONTACT AND INFORM OF OUR
POLICY ON ANTIFREEZE.

Karen Chandler & I investigated this complaint and
found that Seminole Amoco catches their spent Antifreeze
and puts it in 55 gallon drums. They have SW Petroleum
pick it up. We talked to Don Miller at the station.

(over)

ADDRESS

2152 S. Glenstone

2152 S. Glenstone

July 30, 1981

Mr. John DeWeese, District Manager
Standard Oil Company
725 E. Edgewood
Springfield, Missouri 65807

Dear Mr. DeWeese:

Personnel from this office reinspected the Seminole Standard Service Station at 2152 S. Glenstone on Thursday, July 30, 1981. At that time we found the hole in the southern most wall of the service station had been concreted up. This will apparently take care of any problem with material draining from the inside of the station to the outside lot.

Thank you for your prompt action in correcting this problem.

Yours truly,

Gene Pabst
Water Pollution Control Inspector III
Surveillance & Enforcement

GP:js

2152 S. Glenstone



JUL 23 1981

Action Note

This informal note makes possible immediate response . . . and we hope you will agree that in this instance promptness is more important than formality. If reply is made, please send to:

Stoddard Equip Co.
3536 E. Sunshine
Springfield, Mo 65804

Subject	Attention/Account	Date
Sumner Standard		7-20-81

2152 S. Hurst
Springfield, Mo 65804

I am authorizing you to plug a hole in the outside wall of the building located near the Southern Meat stall. This needs to be done as soon as possible to comply with City, State and Fed. Law. Please Advise when completed.

cc: Mr Gene Parrot



No Reply Required

City of Springfield

Signed

John Newell

Date

Mr Gene Parrot

Stoddard Equipment Co. will plug hole & advise.

John Newell

Signed

July 8, 1981

Mr. John DeWeese, District Manager
Standard Oil Company
725 E. Edgewood
Springfield, Missouri 65807

Dear Mr. DeWeese:

Recently personnel from this office noticed an oily substance to the south of the Seminole Standard Service Station at 2152 S. Glenstone. Upon investigation it was found that the southern most stall in the service station did not have a floor drain and that a hole was drilled through the outside wall to allow drainage out of the building.

This is a direct violation of City, State, and Federal Law. Steps should be taken immediately to eliminate this problem. The problem can be corrected by plugging up the hole through the wall and discontinuing all washing operations in this area. Or, you can plug the hole in the wall and install a floor drain, which would be attached to the sanitary sewer. This floor drain should have a sump to catch all spillage of oil and allow settling of solids.

Please notify this office within 15 days as to what steps you plan to take to correct this problem.

If you have any questions, please feel free to call. The phone number is 864-1924.

Yours truly,

Gene Pabst
Water Pollution Control Inspector III
Surveillance & Enforcement

GP:js

2152 S. Glenstone